


PWL LOCKING OVERSHOT



	ITEM DESCRIPTION	PART NUMBERS
1-25	PWL LOCKING OVERSHOT	26-00-300
1	OVERSHOT EYE BOLT	26-00-001
2	CABLE SWIVEL COLLAR	26-00-002
3	OVERSHOT BRASS BEARING WASHER - 2 NOS.	26-00-003
4	OVERSHOT SLOTTED NUT	26-00-004
5	OVERSHOT COTTER PIN	26-00-005
6	GREASE FITTING	16-01-019
7	CABLE SWIVEL BODY	26-00-007
8	OS JAR STAFF ASSY	26-00-008
9	OS JAR TUBE ASSY	26-00-009
10	OS HEX NUT	26-00-010
11	OS SPRING WASHER	26-00-011
12	LOCKING OS CAP	26-00-012
13	LOCKING OS CAP SPRING	26-00-013
14	LOCKING OS SLEEVE	26-00-014
15	LOCKING OS SS BALL COMP. SPRING	26-00-015
16	LOCKING OS SS BALL 11/32" - 2 NOS.	26-00-016
17	LOCKING OVERSHOT HEAD	26-00-017
18	LIFTING DOG COMPRESSION SPRING	26-00-018
19	LIFTING DOG N	26-00-019
20	PWL OS SOLID PIN 1/2" X 3-1/2"	26-00-029
21	NWL OS SPRING DOWELL 1/4" X 1-3/4"	26-00-021
22	OS LOCKING PIN	26-00-022
23	LOCKING OS GRUB	26-00-023
24	OS RELEASING SLEEVE	26-00-024
25	PWL OVERSHOT ADAPTOR	26-00-026